



AD

AD625928

CCL REPORT NO. 190

EXTENDED USE OF IMPROVED COOLING SYSTEM
INHIBITOR - FIELD EVALUATION

INTERIM REPORT

BY

JAMES H. CONLEY

3 DECEMBER 1965

0.50 0.50 / 2 a

Co-2 1

AMCMS CODE NO. 5025.11.803
DA PROJECT IC024401A109

U. S. ARMY COATING & CHEMICAL LABORATORY

Aberdeen Proving Ground
Maryland

UNCLASSIFIED

CCL REPORT NO. 190

EXTENDED USE OF IMPROVED COOLING SYSTEM
INHIBITOR - FIELD EVALUATION

BY

JAMES H. CONLEY

3 DECEMBER 1965

AMCMS CODE NO. 5025.11.803

DEPARTMENT OF THE ARMY PROJECT NO.
1C024401A109

U. S. ARMY COATING AND CHEMICAL LABORATORY
ABERDEEN PROVING GROUND
MARYLAND

UNCLASSIFIED

ABSTRACT

The object of this investigation is to determine if Federal Specification 0-1-490a, Corrosion Inhibitor is suitable for use in vehicle cooling systems for extended periods. The improved inhibitor was placed in the vehicle cooling systems with antifreeze compounds meeting Federal Specification 0-A-548a, Type I, or commercial materials similar to the Type I. The inhibitor was added at the rate of 1 ounce per 2 quarts of water used in making up the antifreeze solution. Four government vehicles and four private passenger cars were utilized for test. Solutions were checked every three months and if necessary the coolant freezing point, pH value and reserve alkalinity (R.A.) value were adjusted.

Data indicates that inspection periods of longer than three months permits the coolant to get out of control. In the event the Army adopts the continued use of antifreeze solutions for two years, the coolant solutions must be checked every three months by technical personnel and adjusted, if necessary, to insure safe continued use.

TABLE OF CONTENTS

| | Page No. |
|----------------------------------|----------|
| TITLE PAGE | i |
| ABSTRACT | ii |
| INTRODUCTION | 1 |
| DETAILS OF TEST | 1 - 2 |
| RESULTS | 2 - 3 |
| DISCUSSION AND CONCLUSIONS | 3 |
| REFERENCES | 3 |
| DISTRIBUTION LIST | 4 - 6 |
| APPENDIX A | 7 |
| Table I | 7 - 9 |
| DD FORM 1473 | 10 |

I. INTRODUCTION

Aberdeen Proving Ground, Maryland, was directed by AMC program directive AMCMS Code 5025.11.803, dated 24 July 1964 to investigate improved antifreeze mixtures.

Several inhibitor systems were examined in both glassware bench corrosion tests and simulated service tests. Data reported in CCL Reports Nos. 125, 145, 155 and 156 showed that glassware bench tests gave satisfactory results with cast iron-aluminum systems. Data also showed that in simulated service tests utilizing cast iron-aluminum systems corrosion was evident using Federal Specification 0-A-548a Type I antifreeze inhibited with Federal Specification 0-1-490 corrosion inhibitor. CCL Report No. 156 showed that by adding phosphate the corrosion in a cast iron-aluminum system was greatly reduced. As a result of this Federal Specification 0-1-490a was issued. Field tests were set up. Preliminary results were recorded in CCL Report No. 156.

This interim report contains additional data on the field evaluation of the improved inhibitor.

II. DETAILS OF TEST

A. Vehicles.

Two test vehicles, two facility vehicles and four civilian vehicles were utilized for the field evaluation. All the vehicles except one contained a cast iron block and head and a copper radiator. One civilian vehicle had a cast iron block and aluminum head and a copper radiator.

B. Test Solution.

The two test vehicles and two facility vehicles were filled with Federal Specification 0-A-548a, Type I antifreeze, and distilled water containing Federal Specification 0-1-490a, Corrosion Inhibitor. The inhibitor was added at the rate of 5 ounces per 10 quarts of water used.

The four civilian vehicles were filled with commercial antifreeze compounds purchased by the vehicle owners. These antifreeze compounds were similar in nature to the Type I antifreeze and were adjusted to contain approximately the same inhibitor system as the two test vehicles and two facility vehicles.

Solution concentrations are indicated by the freeze points in table I of the Appendix.

C. Preparation for Test.

All vehicles were drained and flushed. All unserviceable parts were replaced. The vehicles were then filled with the test solution. A sample was taken and the initial pH, reserve alkalinity (P. A.), and freezing point data recorded.

D. Sampling and Solution Check.

The sampling on the two test vehicles was made at approximately every 5,000 miles.

The sampling on the two facility vehicles was made at approximately every four to six months.

The sampling on the four civilian vehicles was made every three months.

The pH, reserve alkalinity (R.A.), and freezing point of the coolant were determined at each inspection. Adjustments, if necessary, for coolant level, pH, R.A. and freezing point were made at each inspection.

III. RESULTS

Results of the tests are listed in Table I of the Appendix. The two test vehicles were intended to be run for 20,000 miles but at approximately 10,000 miles each vehicle had a failure not attributed to the antifreeze inhibitor system. The test solutions were lost and the tests stopped.

The two facility vehicles both show that even though they were being monitored by the laboratory, water was being added to the cooling systems in the field by the drivers. One was recharged after 24 months and the test is continuing. Both vehicles were two years old at the start of the test.

The four civilian vehicles were checked every three months and the systems were not tampered with by the drivers between checks. All coolant adjustments were made by the laboratory. Civilian vehicles nos. 1 & 2 are continuing with good service and no difficulty. Both of these vehicles were filled with the antifreeze test solution soon after they were purchased. The cooling system of civilian vehicle no. 3 constantly had to be refilled, sometimes with water and sometimes with antifreeze make up solution. A leak was indicated but was not located. The test on this vehicle was started after it was approximately 1 year old. Civilian vehicle no. 4 was 4 years old when the test began. It had to be recharged after a leak developed around the filler neck at nine months and again twenty one months later when a heater hose broke and

the solution was lost. This vehicle test is continuing.

IV. DISCUSSION AND CONCLUSIONS

The data shows that the inhibitor system under test caused no malfunction of any vehicle tested. The coolant inhibitor performance was satisfactory in every vehicle. There was no coolant loss due to foaming. There was no corrosion of metal parts causing leaks. There were no hose leaks which could be attributed to attack by the coolant.

The data also shows that with proper maintenance and constant checking of the chemical and physical properties of the coolant by technical personnel at three month intervals, the coolant inhibited with Federal Specification 0-1-490a Corrosion Inhibitor can be used in excess of 24 months without serious inhibitor depletion.

Equally important to safe continuous use is the conscientious checking and reporting of coolant system irregularities to the monitoring agency by the vehicle driver as soon as the irregularities are noted. No adjustments to the coolant should be made by the driver unless it is virtually impossible to move the vehicle without damage to the engine.

Data also indicates that the older the vehicle the more frequently breakdowns occur. In order to maintain a coolant system at maximum efficiency for extended periods very close control and constant maintenance will be required of both the monitoring agency and the vehicle driver.

V. REFERENCES

1. AMC program directive AMCMS code 5025.11.803 dated 24 July 1964.
2. Federal Specification 0-1-490, Inhibitor, Corrosion, Liquid Cooling System, dated 27 November 1957.
3. Federal Specification 0-1-490a, Inhibitor, Corrosion, Liquid Cooling System, dated 26 April 1965.
4. Federal Specification 0-A-548a, Antifreeze, Ethylene Glycol, Inhibited, dated 30 Dec. 1958.
5. CCL Report No. 125 - Compatibility of Coolants with Automotive Cooling Systems Containing Aluminum Components - 1st Report, dated 21 June 1962.
6. CCL Report No. 145 - Final Report on Compatibility of Coolants with Automotive Cooling Systems Containing Aluminum Components, dated 14 June 1963.
7. CCL Report No. 155 - New Corrosion Inhibitors for Antifreezes, dated 16 January 1964.
8. CCL Report No. 156 - The Development of an Improved Cooling System Corrosion Inhibitor, dated 10 February 1964.

DISTRIBUTION LIST FOR AMCMS CODE NO. 5025.11.803

| <u>Department of Defense</u> | <u>No. of Copies</u> |
|--|----------------------|
| Defense Documentation Center Cameron Station Alexandria, Virginia 22314 | 20 |
| <u>Department of the Army - Technical Service</u> | |
| Commanding General U.S. Army Materiel Command ATTN: AMCRD-RC Washington, D. C. 20315 | 1 |
| Continental Army Command Department of the Army Fort Monroe, Virginia 23351 | 3 |
| Commanding General U.S. Army Tank-Automotive Center ATTN: Mr. J. P. Jones Warren, Michigan 48090 | 1 |
| Commanding Officer Frankford Arsenal ATTN: SMUFA 1320 Library Philadelphia, Pa. 19137 | 1 1 |
| Commanding Officer U.S. Army Materials Research Agency Watertown Arsenal ATTN: Technical Information Center Watertown, Massachusetts 02172 | 2 |
| Commanding Officer Yuma Proving Ground Arizona 85364 | 1 |
| Commanding General U.S. Army Weapons Command ATTN: AMSWE-RDR Rock Island, Illinois 61200 | 2 |
| Commanding Officer U.S. Army Chemical Research & Development Laboratories ATTN: Librarian Edgewood Arsenal, Maryland 21040 | 1 |

DISTRIBUTION LIST CONTINUED

| | <u>No. of Copies</u> |
|---|----------------------|
| U.S. Army Engineer Research and Development Laboratories ATTN: STINFO Branch Fort Belvoir, Virginia 22060 | 2 |
| Commanding Officer Rock Island Arsenal ATTN: Laboratory 9320 Rock Island, Illinois 61200 | 1 |
| Commanding Officer U.S. Army Ballistic Research Laboratories ATTN: Mr. R. Elchelberger Mr. J. Sperrazza Aberdeen Proving Ground, Maryland 21005 | 1 1 |
| Technical Library Aberdeen Proving Ground, Maryland 21005 | 2 |
| <u>Department of the Navy</u> | |
| Department of the Navy c/o Navy Liaison Aberdeen Proving Ground, Maryland 21005 | 1 |
| Department of the Navy Chief, Bureau of Naval Weapons Washington 25, D. C. | 1 |
| <u>Other Government Agencies</u> | |
| Scientific and Technical Information Facility ATTN: NASA Representative (S-AK/DL) P. O. Box 5700 Bethesda, Maryland 20014 | 3 |
| Chief, Input Section Clearinghouse for Federal Scientific and Technical Information, CFSTI Sills Building 5285 Port Royal Road Springfield, Virginia 22151 | 25 |

DISTRIBUTION LIST CONTINUED

| <u>Foreign Address</u> | <u>No. of Copies</u> |
|---|----------------------|
| Commander British Army Staff British Embassy 3100 Massachusetts Ave., N. W. Washington, D. C. | 2 |
| Canadian Army Staff Canadian Liaison Office Headquarters, U.S. Army Materiel Command Washington, D. C. | 2 |

APPENDIX A

TABLE I

| FIELD TEST DATA | | | | | | | |
|------------------------------|----------------|---------|------|-------|--------------|---------------------|--|
| Vehicle | Operating Time | Mileage | pH | R.A. | Freeze Point | Added at Laboratory | Remarks |
| Test Vehicle #1 | -- | 0 | 7.68 | 9.20 | -12°F. | -- | Start test |
| | 2 weeks | 5098 | 7.62 | 9.00 | -12°F. | 12 qts. make up | Break down in the field |
| | 5 weeks | 9300 | 7.72 | 7.30 | - 4°F | | Test stopped, radiator damaged |
| Test Vehicle #2 | -- | 0 | 7.68 | 9.45 | -13°F | -- | -- |
| | 2 weeks | 4857 | 7.60 | 9.20 | -13°F | -- | -- |
| | 4 weeks | 8479 | 7.62 | 9.00 | -16°F | 3½ qts. make up | -- |
| | 5 weeks | 10800 | -- | -- | -- | -- | Test stopped, head pulled, sol'n. lost |
| Facility Vehicle #1 | -- | 0 | 7.60 | 10.50 | -15°F | -- | Start test |
| | 4 months | 12470 | 7.52 | 9.85 | -24°F | -- | -- |
| | 8 months | 24247 | 7.42 | 9.00 | -23°F | -- | -- |
| | 13 months | 33910 | 7.38 | 7.60 | -22°F | 1 qt. make up | -- |
| | 18 months | 41192 | 7.35 | 7.80 | -22°F | 1½ qts. make up | Heater leak repaired |
| | 24 months | 50726 | 7.48 | 4.10 | + 4°F | -- | Test stopped, sol'n. diluted |
| Facility Vehicle #1 Recharge | -- | 0 | 7.62 | 11.10 | -32°F | -- | Restart test |
| | 2 months | 3277 | 7.60 | 10.50 | -32°F | 2½ qt. make up | Thermostat replaced |
| | 8 months | 12570 | 7.42 | 7.40 | -27°F | -- | Test continuing |

TABLE 1 - Cont'd.

| FIELD TEST DATA | | | | | | | |
|-----------------------------|----------------|---------|------|-------|--------------|-----------------------|--|
| Vehicle | Operating Time | Mileage | pH | R.A. | Freeze Point | Added at Laboratory | Remarks |
| Civilian Vehicle #3 Cont'd. | 11 months | 9439 | 8.08 | 8.80 | -9°F | 1 qt. water | -- |
| | 16 months | 18342 | 7.98 | 9.30 | -17°F | 1½ qts. make up | -- |
| | 20 months | 23218 | 8.10 | 8.60 | -14°F | -- | -- |
| | 23 months | 26226 | 7.98 | 7.90 | -13°F | 1 qt. make up | -- |
| | 26 months | 31863 | 7.93 | 7.90 | -12°F | 2 qts. make up | -- |
| | 28 months | 33662 | 7.95 | 8.40 | -12°F | 1 qt. make up | -- |
| | 32 months | 36073 | 8.13 | 8.00 | -9°F | -- | -- |
| | 35 months | 39229 | 7.90 | 8.00 | -9°F | -- | -- |
| | 36 months | 41779 | 7.90 | 8.00 | -9°F | 1 pt. make up | -- |
| | 37 months | 42355 | 7.95 | 8.20 | -10°F | 1½ qts. make up | -- |
| | 41 months | 45795 | 7.98 | 8.50 | -13°F | 3 qts. make up | -- |
| | 42 months | 46887 | 8.13 | 8.40 | -13°F | 1 gal inhibited water | Test stopped, restarted |
| Civilian Vehicle #4 | -- | 0 | 8.20 | 13.80 | -22°F | -- | Start test |
| | 3 months | 3295 | 8.15 | 12.85 | -22°F | -- | -- |
| | 5 months | 4884 | 8.12 | 11.00 | -11°F | 2 qts. water | -- |
| | 8 months | 7868 | 8.32 | 8.50 | + 2°F | 4 qts. water | Test stopped. Leak around top filler outlet. Restarted. |
| Civilian Vehicle #4 Repeat | -- | 0 | 8.18 | 14.30 | -14°F | -- | Start test |
| | 6 months | 1299 | 8.00 | 14.10 | -14°F | -- | -- |
| | 9 months | 3623 | 7.98 | 13.10 | -14°F | -- | -- |
| | 18 months | 8686 | 7.95 | 11.40 | -14°F | 1 qt. make up | -- |
| | 21 months | 12245 | -- | -- | -- | -- | Hose brake, sol'n. lost, systems re-charged & continuing |

TABLE 1 - Cont'd.

FIELD TEST DATA

| Vehicle | Operating Time | Mileage | pH | R.A. | Freeze Point | Added at Laboratory | Remarks |
|-------------------------------------|--|--|--|---|---|--|--|
| Facility Vehicle #2 | -- 4 months 8 months 16 months 22 months | 0 12560 20043 24132 35277 | 7.52 7.45 7.50 7.50 7.90 | 11.00 10.40 8.60 7.40 6.10 | -19°F -30°F -22°F -11°F + 4°F | -- -- -- 1½ qts. make up -- | Start test -- -- -- Test stopped, sol'n. diluted |
| Civilian Vehicle #1 (Aluminum Head) | -- 6 months 9 months 12 months 15 months 18 months 21 months | 0 7770 14537 19676 22935 27302 33045 | 8.10 8.18 8.18 7.95 7.95 8.00 8.00 | 12.50 11.40 10.70 10.20 10.10 10.10 10.10 | -14°F -14°F -14°F -14°F -14°F -14°F -14°F | -- -- 1 pt. rake up -- -- -- -- | Start test -- -- -- -- -- Test continuing |
| Civilian Vehicle #2 | -- 6 months 9 months 13 months 21 months 24 months | 0 5066 7766 11745 17820 19617 | 8.23 8.20 8.12 7.92 7.92 7.92 | 13.70 12.70 12.10 11.60 11.36 11.20 | -14°F -14°F -14°F -14°F -14°F -14°F | -- -- -- -- -- 1 pint make up | Start test -- -- -- -- -- Pressure cap replaced Test continuing |
| Civilian Vehicle #3 | -- 2 months 5 months 6 months 8 months | 0 1494 3501 4187 7143 | 8.15 8.12 8.02 8.08 8.12 | 11.50 10.80 10.80 10.00 9.15 | -24°F -20°F -21°F -17°F -12°F | -- 1 qt. water -- 2 qts. water 1½ qts. water | Start test -- -- -- -- |

UNCLASSIFIED

Security Classification

| DOCUMENT CONTROL DATA - R&D | | |
|---|--|--|
| (Security classification of title, body of abstract and indexing annotation must be entered when the overall report is classified) | | |
| 1. ORIGINATING ACTIVITY (Corporate author) U.S. Army Coating and Chemical Laboratory Aberdeen Proving Ground, Maryland | | 2a. REPORT SECURITY CLASSIFICATION Unclassified |
| | | 2b. GROUP |
| 3. REPORT TITLE EXTENDED USE OF IMPROVED COOLING SYSTEM INHIBITOR - FIELD EVALUATION | | |
| 4. DESCRIPTIVE NOTES (Type of report and inclusive dates) INTERIM | | |
| 5. AUTHOR(S) (Last name, first name, initial) CONLEY, JAMES H. | | |
| 6. REPORT DATE NOVEMBER 1965 | 7a. TOTAL NO. OF PAGES | 7b. NO. OF REFS 8 |
| 8a. CONTRACT OR GRANT NO. AMCMS CODE #5025.11.803 b. PROJECT NO. IC024401A109 c. d. | 9a. ORIGINATOR'S REPORT NUMBER(S) CCL #190 9b. OTHER REPORT NO(S) (Any other numbers that may be assigned this report) | |
| 10. AVAILABILITY/LIMITATION NOTICES Qualified requesters may obtain copies of this report from Defense Documentation Center. Copies Available at Office of Technical Services, \$ 0.50. | | |
| 11. SUPPLEMENTARY NOTES | 12. SPONSORING MILITARY ACTIVITY U.S. Army Materiel Command Washington, D. C. 20315 | |
| 13. ABSTRACT The object of this investigation is to determine if Federal Specification 0-1-490a, Corrosion Inhibitor is suitable for use in vehicle cooling systems for extended periods. The improved inhibitor was placed in the vehicle cooling systems with antifreeze compounds meeting Federal Specification 0-A-548a, Type I, or commercial materials similar to the Type I. The inhibitor was added at the rate of 1 ounce per 2 quarts of water used in making up the antifreeze solution. Four government vehicles and four private passenger cars were utilized for test. Solutions were checked every three months and if necessary the coolant freezing point, pH value and reserve alkalinity (R.A.) value were adjusted. Data indicates that inspection periods of longer than three months permits the coolant to get out of control. In the event the Army adopts the continued use of antifreeze solutions for two years, the coolant solutions must be checked every three months by technical personnel and adjusted, if necessary, to insure safe continued use. | | |